

Wiener HV Table Mistakes/Discrepancies

1. There is no entry for **hv-1_u110**
 - a) "Set Voltage" is 1675 V
 - b) Tanks S7, R7

2. Discrepancy for **hv-1_u113** tanks
 - a) Tanks listed in the table are P10, P7, but these tanks are slated for slot 20 in the FEB 4 crate table on the Electronics configuration web page.
 - b) Tanks are Q10, Q7 on same web page, under FEB 3 crate

3. Discrepancy for **hv-1_u114** tanks
 - a) Tanks listed in the table are P9, P8, but these tanks are slated for slot 20 in the FEB 4 crate table on the Electronics configuration web page.
 - b) Tanks are Q9, Q8 on same web page, under FEB 3 crate